

Bombardier has issued Service Bulletin 670BA-28-027 which replaces the Ejector P/N T99A38-603 with P/N T99A38-606. According to SB 670BA-28-027 replacement of this Ejector eliminates the need to perform the leak check that is required in SB 670BA-28-025.

Is AD 2004-18-03 necessary for the aircraft that have SB 670BA-28-027 incorporated?